



CROWN SUPER ACRYLIC WHITE

PRODUCT DATA SHEET NO.: L-139

DATE: Feb 2007

PRODUCT CODE: CSA 1

THIS SUPERSEDES ALL PREVIOUS PUBLICATIONS

Product Description	Good quality acrylic emulsion paint for interior and exterior use.		
Intended Uses	<ul style="list-style-type: none"> Suitable for application to suitably primed new cement plaster, concrete, porous brickwork and various types of building boards. May also be applied to suitably primed wood, metals, fibre-cement and gypsum plaster. 		
Features	<ul style="list-style-type: none"> Good interior and exterior durability and low odour. Easy to clean with good scrubability. Good obliteration and excellent spreadability. 		
Product Information	Appearance	White : Smooth matt	
	Colours	Colours : Smooth low sheen...no standard colours? White and standard colours as per colour card. Also available in a very wide range of Inspired Colour tints.	
	Generic type	Modified acrylic emulsion	
	Solids	approx. 57 % by mass; 39 % by volume (typical for white)	
	S G	1,41 (typical for white)	
	Recommended DFT	Min.: 20 µm	Max.: 35 µm
	Practical spreading rate	9 m ² /λ (typical)	
	Viscosity at 23 °C	Approx. 90 KU	
	Dry temp resistance	Continuous	: 65 °C
		Non-continuous	: 90 °C
	Flash point	Non-flammable	
Application Details	Mixing	Stir thoroughly with a flat paddle until homogeneous.	
	Method	Brush, roller or airless spray.	
	Substrate	Thoroughly cleaned, unprimed or primed concrete, cement plaster, brickwork, building boards and suitably primed wood, metal, fibre-cement and gypsum plaster.	
	Thinning	<ul style="list-style-type: none"> Not normally required for non-porous surfaces. For porous surfaces thin first coat only 10 parts Crown Homestead Super Acrylic to 1 part water by volume. 	
	Cleaning	Water	
	Application Environment	Surface Temperature	Ambient Temperature Relative Humidity
		Min.: 5 °C	Min.: 5 °C -
		or 2 °C min. above dew point	
		Max.: 40 °C	Max.: 40 °C Max.: 85 %
	Drying time	Touch dry	30 min at 23 °C
		Dry to handle	1 h at 23 °C
		Recoating	1 h at 23 °C
Storage and Packaging	Store away from direct sun, heat and severe cold. Packaging: 5 l and 20 l		

Crown Super Acrylic White

Surface Preparation	<ul style="list-style-type: none"> Ensure that surfaces are dry, sound, and free from dust, dirt, grease and oil before painting. <ol style="list-style-type: none"> NEW WORK <ol style="list-style-type: none"> Cement plaster, concrete: Remove any loose particles and laitance by most suitable means. N.B. Soft, under bound, friable and highly porous surfaces must be restored to a sound condition with PLASCON BONDING LIQUID (CVI 14) (For dry inland areas) or CROWN HOMESTEAD PLASTER PRIMER (for humid and coastal areas) or by replastering - refer to Plascon Technical Services Department. Gypsum plaster (e.g. Rhinolite, Crete stone), brickwork: Apply one coat of CROWN HOMESTEAD PLASTER PRIMER (CHP 1). If a gypsum plaster (e.g. Rhinolite, Crete stone) has been used as the joint skimming filler on gypsum board or dry wall partitioning, then seal these areas with CROWN HOMESTEAD PLASTER PRIMER (CHP 1) PREVIOUSLY PAINTED SURFACES <ol style="list-style-type: none"> Previously painted surfaces in sound condition: Remove loose and flaking paint back to a sound substrate and a firm edge by scraping and sanding. Spot prime with appropriate primer. Clean down with POLYCELL SUGAR SOAP solution to remove all contaminants and chalked material. Rinse with clean water to remove all traces of sugar soap. Alternatively, clean with high pressure water jet. Sand glossy enamel surfaces to a matt finish and apply one coat of CROWN HOMESTEAD UNDERCOAT (CHU 1) Previously painted surfaces in poor condition: Completely remove paint by most appropriate means e.g. scraping, coarse sanding or stripping with STRIPCLEAN SUPER PAINT STRIPPER (PR 17) or POLYCELL PAINT STRIPPER. Then wash thoroughly with POLYCELL SUGAR SOAP. Rinse well with fresh water to remove all traces of the cleaning agents and debris. Ensure substrate is sound, not powdery or friable, prior to coating. Previously lime washed or distempered surfaces: Remove all lime wash by wire brushing, sanding, etc. until plaster is visible. Remove distemper completely. Allow to dry and apply one coat of PLASCON BONDING LIQUID (CVI 14) or CROWN HOMESTEAD PLASTER PRIMER (for coastal areas). N.B. PLASCON BONDING LIQUID must be over coated within 72 hours. FILLING Fill all imperfections with the appropriate Polycell filler and spot prime filled areas with PLASTER PRIMER (PP 700).
Application	<ul style="list-style-type: none"> Thin as recommended. Apply two or three coats to new surfaces to achieve complete obliteration.
Cautions	<ul style="list-style-type: none"> Metal surfaces must be primed as per Surface Preparation above. Avoid painting during inclement weather or if temperature is below 5 °C. To ensure that colours on a project are consistent check that batch numbers are the same.
Safety Precautions	<ul style="list-style-type: none"> Keep out of reach of children. Ensure good ventilation during application and drying. In case of skin contact, wash with soap and water or a recognised skin cleaner. Avoid contact with eyes – In case of contact, rinse eyes immediately with plenty of water and seek medical advice if symptoms persist. If ingested give plenty of water / milk. Do not induce vomiting. Seek medical attention. Refer to Material Safety Data Sheet for complete information.

DISCLAIMER:

The recommendations contained herein are given in all good faith and are meant to guide the specifier or the user. They are based on results gained from our tests and experiences and are believed to be reliable. No guarantee is implied by the recommendations contained herein since conditions of use, method of application and cleanliness of the substrate prior to painting are beyond our control.

N.B.: Technology may change with time necessitating changes to this Product Data Sheet (PDS). It is the responsibility of the user to ensure that the latest PDS is being used.

NB: TO ORDER: Quote product name, product code number, packaging and colour.

PLASCON PAINTS (PTY) LIMITED

CAPE TOWN:

P O Box 42
Eppindust 7475
Tel: (021) 534-6151
Fax: (021) 534-3791

DURBAN:

Private Bag X16
Mobeni 4060
Tel: (031) 451-3200
Fax: (031) 451-3411

MOGALE CITY

(KRUGERSDORP):
Private Bag X4010
Kenmare 1745
Tel: (011) 951-4500
Fax: (011) 955-4136

PORT ELIZABETH:

P O Box 1594
Port Elizabeth 6000
Tel: (041) 401-1400
Fax: (041) 434-606